

Machine Studies/Intervention Schedule for Run 1999-1-1

January 14, 1999, 2000 to January 21,1999, 0800

Time	Thursday, January 14, 1999	Studios
2000-2400	No Beam: SR power supply PEM tests Dipole/trim setup using NMR	Soliday Emery
Time	Friday, January 15, 1999	Studios
0000-0800	No beam, no studies.	
0800-2000	Establish stored beam and working configuration in SR	Borland
2000-2400	Establish stored beam and working configuration in SR	Emery
Time	Saturday, January 16, 1999	Studios
0000-0800	Establish stored beam and working configuration in SR BPM timing scan (if not done already)	Emery
0800-1600	RF setup/checkout with 100mA	Nassiri Borland
1600-2400	BPM/quad offset measurements Make definitive good BPM file (configuration file for orbit correction)	Decker
Time	Sunday, January 17, 1999	Studios
0000-0800	Establish user configuration	Emery
0800-1200	BPM intensity scans	Borland
1200-1600	BPLD validations	Decker
1600-2400	RT feedback system checkout Check RT feedback during filling BPM gain measurements	Carwardine

Time	Monday, January 18, 1999	Studiers
0000-0800	X-BPM translation stage scans	Singh, Shu
0800-1600	Establish configurations for PAR accumulation from rf guns	Lewellen Borland
1600-2400	S34-ID X-BPM stray radiation	Decker
Time	Tuesday, January 19, 1999	Studiers
0000-0800	RT feedback on X-BPMs	Carwardine
0800-1200	Finalize operational configurations for rf guns	Lewellen Pasky
1200-1600	Electron cloud studies	Harkay Rosenberg
1600-2400	SVD correction of beta-y	Emery
Time	Wednesday, January 20, 1999	Studiers
0000-0800	Sextupole offset measurements	Sereno
0800-1000	Operator training	Yao
1000-1600	Instability thresholds	Harkay Milton
1600-1700	Measurement of top-up injection timing jitter	Lenkszus Borland
1700-2400	BTS/SR matching for injection efficiency improvement	Emery
Time	Thursday, January 21, 1999	Studiers
0000-0800	Operational Readiness	Ops
0800-2400	User beam	Ops